

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/7/30	MAKE	YANMAR	MODEL	B50-2B
SERIAL	NO PLATE		STAMP	60537B	
HR METER	11302	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	*1
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れあり CUTS
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING
BKT	FAIR · Attn	摩耗あり WORN
BKT Cylinder	FAIR · Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
右走行モーター周り油漏れ小 AROUND RIGHT TRAVEL MOTOR: OIL LEAKING	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
左操作レバー折損あり LEFT OPERATION LEVER: CHIPPED OFF E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION *1 右走行モーター弱い、高速側へ切り替わらない *1 RIGHT TRAVEL MOTOR: WEAK POWER, UNABLE TO TURN TO HIGH SPEED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。