

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/7/17	MAKE	UNI CARRIERS	MODEL	711-2
SERIAL	56X30027		STAMP	B12-30??? SOME LETTERS: UNREADABLE	
HR METER	5425	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		TIRE SIZE	12-16.5 8PR	

ENGINE : MODEL	S/N
Oil leakage	FAIR · <u>Attn</u> *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · <u>Attn</u> 効かない NOT WORKING
PARKING BRAKE	FAIR · <u>Attn</u>
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · <u>Attn</u> 破れあり CUTS
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
FRONT & CYLINDERS	
Arm	FAIR · Attn
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / <u>LEVER STEERING</u>	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	<u>YES</u> · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>
COMMENT	
安全レバー効かない SAFETY LEVER: MALFUNCTION	
水温計故障あり WATER TEMPERATURE GAUGE: MALFUNCTION	
マフラーサイレンサー破損あり MUFFLER SILENCER: BROKEN	
下周り油漏れ跡あり BOTTOM: OIL LEAKING TRACE	
*1 ヘッドカバー周り、オイルパン周り油漏れ小	
*1 AROUND HEAD COVER & AROUND OIL PAN: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。