

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2023/10/19	MAKE	CAT	MODEL	313CSR
SERIAL	CAT0313CCWSA00224		STAMP	CAT0313CCWSA00224	
HR METER	1698 + 3407	HR	YEAR	YR	
CAB/CNP	ROPS CAB (/ CAB /)	ROPS CNP / CNP / NONE	SHOE	500G PADS	

ENGINE : MODEL		S/N	6LK28590
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	

BOOM / ARM / BKT			
Boom	FAIR	Attr	破れあり CUTS
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	

BKT	(STD /)	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG	WRIST
Multi	MULTI	2 · NO
ARM-CRANE	YES · NO	スイッチ入らない UNABLE TO TURN ON
BLADE	YES · NO	
OFFSET	YES · NO	
OFFSET Cylinder	FAIR	Attn
Piping	YES · NO	Breaker only · Multi

COMMENT	
CABドアラッチ不良 (外から開かない)	
DOOR LATCH: MALFUNCTION (UNABLE TO OPEN FROM THE OUTSIDE)	

--	--

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。