

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/8/20	MAKE	SUMITOMO	MODEL	SC650DD-2
SERIAL No.	PLATE :	SC065-1459	STAMP	SC065-1459	
HR METER	6144	HR	SHOE	810FLAT	YEAR YR

ENGINE : MODEL	S/N
Oil leakage	FAIR ☒ Attn ブロックにじみあり ENGINE BLOCK: OIL OOZING
Blow-By	FAIR ☒ Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn
Oil	FAIR ☒ Attn
Exhaust Color	FAIR ☒ Attn

OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	にじみあり OIL OOZING
Power	FAIR・Attn	

COOLING SYSTEM		
Radiator	FAIR・Attn	コア潰れあり CORE: BROKEN
Oil Cooler	FAIR・Attn	

OPERATING SYSTEM		
Computer	OK・NG	未確認 NOT CHECKED
Swing	FAIR・Attn	
Travel	FAIR・Attn	

BOOM		
MAIN BOOM		TOP, BOTTOM, 9m × 2, 6m × 1
BOOM TOTAL		36m
TOP SHEAVE	YES · NO	
JIB		
TOWER		

INTERIOR	See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR ☒ · DIRTY
Operator's Seat	FAIR ☒ Attn
Glasses	FAIR ☒ Attn
AirCon	A/C ☒ · H/C · H only · C only · None

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

COMMENT

左右キャタたるみあり TRACK LINKS: WORN

WEIGHT	3	
HOOK	65t, 30t, BALL	
FREE FALL	YES · NO	
LIFTER	YES · NO	

COMMENT	
穴あり BODY: MUCH HUGE HOLES	
ハイCAB HIGH CAB	
オルタネータ不良 ALTERNATOR: MALFUNCTION	
アクセルグリップ不良、E/G回転上がらない	
ACCELERATOR GRIP: MALFUNCTION (NOT REVVING UP)	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1	
@SHIROI YARD	
BOOM: 9m × 2	
HOOK: 30t, BALL	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。