

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2023/3/13	MAKE	CAT	MODEL	962H
SERIAL	CAT0962HVJ6J00176		STAMP	CAT0962HVJ6J00176	
HR METER	18623	HR	Odometer	66864	km
YEAR					YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5R25	

ENGINE : MODEL S/N	UNDERCARRIAGE : See Photos. 写真参照
Oil leakage <input checked="" type="radio"/> FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
Blow-By <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE	COMMENT
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA YES · <input checked="" type="radio"/> NO *1	STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING
OPERATION PUMP	RIDE CONTROL <input checked="" type="radio"/> YES · <input type="radio"/> NO
Sound <input checked="" type="radio"/> FAIR · Attn	ATTACHMENTS
Oil leakage <input checked="" type="radio"/> FAIR · Attn	STD BKT <input checked="" type="radio"/> YES · <input type="radio"/> OTHER
Power <input checked="" type="radio"/> FAIR · Attn	BLADE YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COOLING SYSTEM	COMMENT
Radiator <input checked="" type="radio"/> FAIR · Attn	*1 ステッカー一部読み取り不可 STICKER: PARTLY UNREADABLE
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	*2 正面、左側割れあり WINDSHIELDS & LEFT SIDE GLASS: CRACKED
TRANSMISSION & TRAVEL	
T/M TYPE <input checked="" type="radio"/> PS · <input type="radio"/> DD	
Transmission <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE <input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE <input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses FAIR · <input checked="" type="radio"/> Attn *2	
AirCon <input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
FRONT & CYLINDERS	
Arm <input checked="" type="radio"/> FAIR · Attn	
Bell crank <input checked="" type="radio"/> FAIR · Attn	
Bucket <input checked="" type="radio"/> FAIR · Attn	
Articulate <input checked="" type="radio"/> FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。