# INSPECTION SHEET 検品書
## WHEEL LOADER タイヤショベル

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2024/3/13 | MAKE | TCM | MODEL | 705 |
| SERIAL | 56P01209 | | | STAMP | NOT FOUND |
| HR METER | 5203 HR | Odometer | – km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP (CNP) / NONE | | | TIRE SIZE | 27×8.50-15 4PR |

| ENGINE : MODEL | S/N | |
|---|---|---|
| Oil leakage | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | (FAIR) · Attn | |
| Oil | (FAIR) · Attn | |
| Exhaust Color | (FAIR) · Attn | |
| US EPA | YES · (NO) | |
| **OPERATION PUMP** | | |
| Sound | (FAIR) · Attn | |
| Oil leakage | (FAIR) · Attn | |
| Power | (FAIR) · Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR) · Attn | |
| Oil Cooler | (FAIR) · Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | (PS) · DD | |
| Transmission | (FAIR) · Attn | |
| Travel | (FAIR) · Attn | |
| FOOT BRAKE | FAIR · (Attn) | 効かない MALFUNCTION |
| PARKING BRAKE | FAIR · (Attn) | 効かない MALFUNCTION |
| **INTERIOR** | **See Photos. 写真参照** | |
| Operator's Seat | FAIR · (Attn) | 破れあり CUTS |
| Inside Cover | FAIR · Attn | |
| Glasses | FAIR · Attn | |
| AirCon | A/C · H/C · H only · C only · (None) | |
| **FRONT & CYLINDERS** | | |
| Arm | (FAIR) · Attn | |
| Bell crank | FAIR · Attn | |
| Bucket | FAIR · (Attn) | 腐食、穴大 CORRODED & MUCH HUGE HOLES |
| Articulate | FAIR · Attn | |

| UNDERCARRIAGE : See Photos. 写真参照 | | | |
|---|---|---|---|
| **RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | |
| **COMMENT** | | | |
| STEERING TYPE | WHEEL STEERING / COMMAND STEERING / (LEVER STEERING) | | |
| RIDE CONTROL | YES · (NO) | | |
| **ATTACHMENTS** | | | |
| STD BKT | (YES) · OTHER | | |
| BLADE | YES · (NO) | Piping for Tilt | (YES) · NO |
| **COMMENT** | | | |
| 各警告ランプ点灯あり MANY WARNING LAMPS: ON | | | |
| 安全レバー効かない SAFETY LEVER: MALFUNCTION | | | |
| 燃料キャップカバー欠品 FUEL FILLER PORT COVER: MISSING | | | |
| **RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。