

INSPECTION SHEET 検品書
EXCAVATOR バックホー

| | | | | | |
|-----------------|---|------|--------|-----------|----------|
| INSPECTION DATE | 2024/4/4 | MAKE | YANMAR | MODEL | VIO45-6A |
| SERIAL | 6G492 | | STAMP | 6G492 | |
| HR METER | 1492 | HR | YEAR | YR | |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE | | SHOE | 350G PADS | |

| | | | |
|----------------------------------|---|----------------------------|-------|
| ENGINE : MODEL | | S/N | 47565 |
| Oil leakage | <u>FAIR</u> · Attn | | |
| Blow-By | <u>FAIR</u> · Attn | A LITTLE · MIDDLE · SEVERE | |
| Sound | <u>FAIR</u> · Attn | | |
| Oil | <u>FAIR</u> · Attn | | |
| Exhaust Color | <u>FAIR</u> · Attn | | |
| US EPA | <u>YES</u> · NO | | |
| MAIN PUMP | | | |
| Sound | <u>FAIR</u> · Attn | | |
| Oil leakage | <u>FAIR</u> · Attn | | |
| Power | <u>FAIR</u> · Attn | | |
| COOLING SYSTEM | | | |
| Radiator | <u>FAIR</u> · Attn | | |
| Oil Cooler | <u>FAIR</u> · Attn | | |
| OPERATING SYSTEM | | | |
| Swing | <u>FAIR</u> · Attn | | |
| Travel | <u>FAIR</u> · Attn | | |
| INTERIOR See Photos. 写真参照 | | | |
| Operator's Seat | <u>FAIR</u> · Attn | | |
| Inside Cover | FAIR · Attn | | |
| Glasses | FAIR · Attn | | |
| AirCon | A/C · H/C · H only · C only · <u>None</u> | | |
| BOOM / ARM / BKT | | | |
| Boom | <u>FAIR</u> · Attn | | |
| Boom Cylinder | <u>FAIR</u> · Attn | | |
| Arm | <u>FAIR</u> · Attn | | |
| Arm Cylinder | <u>FAIR</u> · Attn | | |
| BKT | <u>FAIR</u> · Attn | | |
| BKT Cylinder | <u>FAIR</u> · Attn | | |

| | |
|--|---|
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| | |
| BKT | STD / <u>SLOPE</u> / NARROW / SKELETON / OTHER() |
| Lever | LONG · <u>WRIST</u> |
| Multi | <u>MULTI</u> · 2 · NO |
| ARM-CRANE | YES · <u>NO</u> |
| BLADE | <u>YES</u> · NO |
| OFFSET | YES · <u>NO</u> |
| OFFSET Cylinder | FAIR · Attn |
| Piping | <u>YES</u> · NO Breaker only · <u>Multi</u> |
| COMMENT | |
| ワンタッチ付 W/ONE-TOUCH | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。