INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/4/9	MAKE	KOMATSU	MODEL	FG25HT-14
SERIAL	558394			STAMP	M151B-558394
HR METER	16459 HR	Odometer	- km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE			TIRE SIZE	F: 7.00-12 SOLID / R: 6.00-9 SOLID
MAX LIFTING HEIGHT	4.5 m	(VIEW) / MONO		FORK LENGTH	1000 mm
FORK SPEC	フルフリー、サイドシフト付 FULL FREE, W/SIDE-SHIFT				

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	FAIR ・(Attn)	効かない MALFUNCTION
PARKING BRAKE	FAIR ・(Attn)	前進側弱い BRAKE: LOOSE TO GO FORWARD
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR ・(Attn)	破れあり HUGE CUTS
Inside Cover	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・(None)	
HYDRAULICS		
MAST Cylinder	(FAIR)・ Attn	
TILT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT

タイヤ摩耗大 TIRES: MUCH WORN

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。