

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

| | | | | | |
|-----------------|--------------|----------|---------------------------------|-----------|----|
| INSPECTION DATE | 2024/4/16 | CATEGORY | GENERATOR / COMPRESSOR / WELDER | | |
| MAKE | SHIN DAIWA | | MODEL | DGW310MC | |
| SERIAL | W00355003186 | | STAMP | NOT FOUND | |
| HR METER | 2775 | HR | TIRE SIZE | YEAR | YR |

| | | | | | |
|-----------------|------|--------------|----------------------------|---------------|------|
| ENGINE : | | MODEL | KUBOTA D722 | S/N | |
| Oil leakage | FAIR | Attn | | Oil | FAIR |
| Blow-By | FAIR | Attn | A LITTLE · MIDDLE · SEVERE | Exhaust Color | FAIR |
| Sound | FAIR | Attn | | Radiator | FAIR |

| | | | | | |
|------------------|-----------------------------------|------|---------------------------|----------------------|------|
| GENERATOR | | | | | |
| RATED POWER | 6.0 / 9.9 | KVA | Leaking Breaker Condition | FAIR | Attn |
| RATED AMPERE | 30A × 2, 27.3A × 2 / 28.6A, 26.0A | | A | Insulation Condition | FAIR |
| Output Terminal | FAIR | Attn | | | |

| | | | | | |
|---------------------|------|-------------|-------------------------|------|------|
| COMPRESSOR | | | | | |
| RATED PRESSURE | | Mpa Kgf/cm2 | Unload Condition | FAIR | Attn |
| RATED AIR FLOW | | m3/min | Receiver Tank Condition | FAIR | Attn |
| Compressor Oil Leak | FAIR | Attn | Safety Valve Condition | FAIR | Attn |

| | | |
|------------------|------|------|
| CONDITION | FAIR | Attn |
| | | |

| | |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--|---|

| | |
|-----------------|--|
| COMMENTS | |
|-----------------|--|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。