

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

| | | | | | |
|-----------------|---------------|----------|---------------------------------|-----------|----|
| INSPECTION DATE | 2024/4/19 | CATEGORY | GENERATOR / COMPRESSOR / WELDER | | |
| MAKE | NIPPON SHARYO | | MODEL | NES220EM | |
| SERIAL | FJ043500 | | STAMP | NOT FOUND | |
| HR METER | 5609 | HR | TIRE SIZE | YEAR | YR |

| | | | | | |
|-----------------|------|--------------|----------------------------|---------------|------|
| ENGINE : | | MODEL | MITSUBISHI 6D24-TLE2B | S/N | |
| Oil leakage | FAIR | Attn | | Oil | FAIR |
| Blow-By | FAIR | Attn | A LITTLE · MIDDLE · SEVERE | Exhaust Color | FAIR |
| Sound | FAIR | Attn | | Radiator | FAIR |

| | | | | | |
|------------------|---------------------|------|---------------------------|------|------|
| GENERATOR | | | | | |
| RATED POWER | 195 / 220 | KVA | Leaking Breaker Condition | FAIR | Attn |
| RATED AMPERE | 563, 281 / 577, 289 | A | Insulation Condition | FAIR | Attn |
| Output Terminal | FAIR | Attn | | | |

| | | | | | |
|---------------------|------|-------------|-------------------------|------|------|
| COMPRESSOR | | | | | |
| RATED PRESSURE | | Mpa Kgf/cm2 | Unload Condition | FAIR | Attn |
| RATED AIR FLOW | | m3/min | Receiver Tank Condition | FAIR | Attn |
| Compressor Oil Leak | FAIR | Attn | Safety Valve Condition | FAIR | Attn |

| | | |
|------------------|------|------|
| CONDITION | FAIR | Attn |
| | | |

| | |
|---|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|---|---|

| | |
|-----------------|--|
| COMMENTS | |
|-----------------|--|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。