

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

| | | | | | |
|-----------------|---|----------|--------|-----------|----------------|
| INSPECTION DATE | 2024/6/11 | MAKE | YANMAR | MODEL | V3-5 |
| SERIAL | 51555 | | | STAMP | L3D-51555 |
| HR METER | 2155 STOP HR | Odometer | - | km | YEAR YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | | TIRE SIZE | 12.5/70-16 6PR |

| | | | |
|----------------------------------|---|---------------------------------|-------|
| ENGINE : MODEL | | S/N | 71064 |
| Oil leakage | <input checked="" type="radio"/> FAIR | Attn | |
| Blow-By | <input checked="" type="radio"/> FAIR | Attn A LITTLE · MIDDLE · SEVERE | |
| Sound | <input checked="" type="radio"/> FAIR | Attn | |
| Oil | <input checked="" type="radio"/> FAIR | Attn | |
| Exhaust Color | <input checked="" type="radio"/> FAIR | Attn | |
| US EPA | YES · <input checked="" type="radio"/> NO | | |
| OPERATION PUMP | | | |
| Sound | <input checked="" type="radio"/> FAIR | Attn | |
| Oil leakage | <input checked="" type="radio"/> FAIR | Attn | |
| Power | <input checked="" type="radio"/> FAIR | Attn | |
| COOLING SYSTEM | | | |
| Radiator | <input checked="" type="radio"/> FAIR | Attn | |
| Oil Cooler | <input checked="" type="radio"/> FAIR | Attn | |
| TRANSMISSION & TRAVEL | | | |
| T/M TYPE | <input checked="" type="radio"/> PS | DD | |
| Transmission | <input checked="" type="radio"/> FAIR | Attn | |
| Travel | <input checked="" type="radio"/> FAIR | Attn | |
| FOOT BRAKE | <input checked="" type="radio"/> FAIR | Attn | |
| PARKING BRAKE | FAIR · <input checked="" type="radio"/> Attn | 故障あり MALFUNCTION | |
| INTERIOR See Photos. 写真参照 | | | |
| Operator's Seat | FAIR · <input checked="" type="radio"/> Attn | 破れあり CUT | |
| Inside Cover | <input checked="" type="radio"/> FAIR | Attn | |
| Glasses | <input checked="" type="radio"/> FAIR | Attn | |
| AirCon | A/C · H/C · H only · C only · <input checked="" type="radio"/> None | | |
| FRONT & CYLINDERS | | | |
| Arm | <input checked="" type="radio"/> FAIR | Attn | |
| Bell crank | <input checked="" type="radio"/> FAIR | Attn | |
| Bucket | <input checked="" type="radio"/> FAIR | Attn | |
| Articulate | <input checked="" type="radio"/> FAIR | Attn | |

| | |
|---|---|
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING | |
| RIDE CONTROL | YES · <input checked="" type="radio"/> NO |
| ATTACHMENTS | |
| STD BKT | <input checked="" type="radio"/> YES · OTHER |
| BLADE | YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO |
| COMMENT | |
| HRメーター故障あり HR METER: MALFUNCTION | |
| CNP溶接あり CNP FRAME: WELDED | |
| 右側昇降ステップ欠品 RIGHT STEP: MISSING | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | |
| 3 | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。