INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/6/12	MAKE	YANMAR	MODEL	C30R-1
SERIAL	NO PLATE	STAMP	D30RA-11056		
HR METER	1664 HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	320R	TIRE	

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	No. OF GEARS / GEARS
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
Swing	FAIR・Attn	
Articulate	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	

MAIN FRAME		
MAIN FLAME	FAIR・Attn	
VESSEL		
VESSEL	FAIR・Attn	*1
REAR GATE TYPE	NORMAL・L-GATE (FLAT)	
REAR GATE	FAIR・Attn	
UNDERCARRIAGE:	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

COMMENT

F下周り油漏れ小 FRONT PART OF BOTTOM: OIL LEAKING

*1 穴、コンクリ付着あり HUGE HOLES, CONCRETE STAINS

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。