

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/6/20	MAKE	YANMAR	MODEL	VIO30-2
SERIAL	25824B		STAMP	25824B	
HR METER	5485	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		NONE	SHOE	300G PADS

<b>ENGINE : MODEL</b>		<b>S/N</b>	81359
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	
<b>MAIN PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
<b>OPERATING SYSTEM</b>			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<input checked="" type="radio"/> FAIR	<input checked="" type="radio"/> Attn	破れあり CUT
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
<b>BOOM / ARM / BKT</b>			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	<input checked="" type="radio"/> Attn	油漏れ小 OIL LEAKING
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
右側走行モーター周り油漏れ小 AROUND RIGHT TRAVEL MOTOR: OIL LEAKING	
BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · <input checked="" type="radio"/> 2 · NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	<input checked="" type="radio"/> YES · NO シリンダー油漏れ小 CYLINDER: OIL LEAKING
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
<b>COMMENT</b>	
ワンタッチシリンダー油漏れあり ONE TOUCH CYLINDER: OIL LEAKING コントロールバルブ周り油漏れ小 AROUND CONTROL VALVE: OIL LEAKING スイングシリンダー油漏れ小 SWING CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。