

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/3/14	MAKE	CAT	MODEL	349E
SERIAL	CAT0349ETRGH00165		STAMP	CAT0349ETRGH00165	
HR METER	14666 / 14654	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>	<b>S/N</b>	
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	YES · <input type="radio"/> NO	
<b>MAIN PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
<b>INTERIOR</b> See Photos. 写真参照		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	Fひび割れあり WINDSHIELD: CRACKED
AirCon	<input type="radio"/> A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<input type="radio"/> FAIR · Attn	
Boom Cylinder	<input type="radio"/> FAIR · Attn	
Arm	<input type="radio"/> FAIR · Attn	
Arm Cylinder	<input type="radio"/> FAIR · Attn	
BKT	<input type="radio"/> FAIR · Attn	
BKT Cylinder	<input type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
両側ピンブッシュひび割れあり SOME PIN BUSHES: BROKEN	
BKT	<input type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ( )
Lever	LONG · <input type="radio"/> WRIST
Multi	MULTI · 2 · <input type="radio"/> NO
ARM-CRANE	YES · <input type="radio"/> NO
BLADE	YES · <input type="radio"/> NO
OFFSET	YES · <input type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input type="radio"/> NO Breaker only · Multi
<b>COMMENT</b>	
ボディヘコミ多数あり BODY: MUCH DENT	
バックモニター不良 BACK MONITOR: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。