

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/15	MAKE	HITACHI	MODEL	ZX210K-5B
SERIAL	HCMDCKA6C00300278		STAMP	HCMDCKA6C00300278	
HR METER	5680	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 4HK1 S/N

Oil leakage	<input type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn
Oil	<input type="radio"/> FAIR · Attn
Exhaust Color	<input type="radio"/> FAIR · Attn
US EPA	<input type="radio"/> YES · NO

MAIN PUMP

Sound	<input type="radio"/> FAIR · Attn
Oil leakage	<input type="radio"/> FAIR · Attn
Power	<input type="radio"/> FAIR · Attn

COOLING SYSTEM

Radiator	<input type="radio"/> FAIR · Attn
Oil Cooler	<input type="radio"/> FAIR · Attn

OPERATING SYSTEM

Swing	<input type="radio"/> FAIR · Attn
Travel	<input type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照

Operator's Seat	<input type="radio"/> FAIR · Attn 破れあり MUCH WORN
Inside Cover	<input type="radio"/> FAIR · Attn
Glasses	<input type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	<input type="radio"/> FAIR · Attn
Boom Cylinder	<input type="radio"/> FAIR · Attn 両側にじみあり CYLINDERS: OIL OOZING
Arm	<input type="radio"/> FAIR · Attn
Arm Cylinder	<input type="radio"/> FAIR · Attn にじみあり OIL OOZING
BKT	<input type="radio"/> FAIR · Attn
BKT Cylinder	<input type="radio"/> FAIR · Attn サビ、傷あり RUSTY, SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
-----	--

Lever	LONG · <input checked="" type="radio"/> WRIST
-------	---

Multi	<input checked="" type="radio"/> MULTI · 2 · NO
-------	---

ARM-CRANE	YES · <input checked="" type="radio"/> NO
-----------	---

BLADE	YES · <input checked="" type="radio"/> NO
-------	---

OFFSET	YES · <input checked="" type="radio"/> NO
--------	---

OFFSET Cylinder	FAIR · Attn
-----------------	-------------

Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi 5
--------	---

COMMENT

各種警告あり ※要写真参照

WARNINGS DISPLAY FOR ENGINE & CHARGING

リンク、Hリンクガタつき大 I-LINKS & H-LINK: MUCH LOOSE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。