

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/3/15	MAKE	CAT	MODEL	910G
SERIAL	CAT0910GKB9X02424			STAMP	CAT0910GKB9X02424
HR METER	5198	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	440/80R24

ENGINE : MODEL	3064	S/N	6LK44935
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS	DD	
Transmission	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR	Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	
FRONT & CYLINDERS			
Arm	<input checked="" type="radio"/> FAIR	Attn	
Bell crank	<input checked="" type="radio"/> FAIR	Attn	
Bucket	<input checked="" type="radio"/> FAIR	Attn	
Articulate	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
COMMENT		
STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING		
RIDE CONTROL	YES · <input checked="" type="radio"/> NO	
ATTACHMENTS		
STD BKT	<input checked="" type="radio"/> YES · OTHER	
BLADE	YES · <input checked="" type="radio"/> NO	Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT		
E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。