

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/3/15	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC0687		STAMP : TR100-0687		
HR METER	19833	HR	Odometer	276388	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	<input type="radio"/>	Attn	*1
Blow-By	FAIR	<input type="radio"/>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	<input type="radio"/>	Attn	
Oil	FAIR	<input type="radio"/>	Attn	
Exhaust Color	FAIR	<input type="radio"/>	Attn	

OPERATION PUMP

Sound	FAIR	<input type="radio"/>	Attn	
Oil leakage	FAIR	<input type="radio"/>	Attn	
Power	FAIR	<input type="radio"/>	Attn	

COOLING SYSTEM

Radiator	FAIR	<input type="radio"/>	Attn	
Oil Cooler	FAIR	<input type="radio"/>	Attn	

OPERATING SYSTEM

Computer	OK	<input type="radio"/>	NG	*2
Swing	FAIR	<input type="radio"/>	Attn	
Travel	FAIR	<input type="radio"/>	Attn	

TRANSMISSION

Transmission	FAIR	<input type="radio"/>	Attn		
No. OF GEARS	3	GEARS			
No. of DRIVE WHEELS	4	WD			

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	<input type="radio"/>	Attn	破れあり HUGE CUTS
Inside Cover	FAIR	<input type="radio"/>	Attn	
Glasses	FAIR	<input type="radio"/>	Attn	
AirCon	A/C	<input type="radio"/>	H/C · H only · C only · None	

COMMENT

CAB右下ヘコミあり LOWER RIGHT PART OF CAB: DENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input type="radio"/>	Attn
DERRICKING CYL.	FAIR	<input type="radio"/>	Attn にじみあり OIL OOZING
EXTENSION CYL.	FAIR	<input type="radio"/>	Attn
JIB	YES	<input type="radio"/>	NO
JIB TYPE	STD	<input type="radio"/>	PWR
MAIN & SUB WIRE	YES	<input type="radio"/>	NO
HOOK	4.9t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

.....
.....
.....

OUTRIGGERS

OUTRIGGERS	X	<input type="radio"/>	H
OUTRIGGERS COND.	FAIR	<input type="radio"/>	Attn

COMMENT

後ろヘコミあり REAR PART OF BODY: DENT
*1 E/G下周り油漏れ、シリンダーヘッド付近にじみあり
*1 BOTTOM: OIL LEAKING, AROUND CYLINDER HEAD: OIL OOZING
*2 画面ひび割れ、映り悪い MONITOR: CRACKED, BLURRED

.....
.....
.....
.....
.....
.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。