

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/3/15	MAKE	KOBELCO	MODEL	RK160-5
SERIAL No.	PLATE : EW04-06041		STAMP : T002-5042		
HR METER	14462	HR	Odometer	171488	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · <input checked="" type="radio"/> MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn 公道自走不可 UNABLE TO RUN ON PUBLIC ROADS
<b>TRANSMISSION</b>	
Transmission	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn *1
No. OF GEARS	4 GEARS
No. of DRIVE WHEELS	4 WD
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れ大 HUGE CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>COMMENT</b>	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	<input checked="" type="radio"/> STD · PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	16t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn *2
<b>COMMENT</b>	
冷却水温上昇あり COOLANT: HIGH TEMPERATURE	
作動油ホースにじみあり HYDRAULIC OIL HOSE: OIL OOZING	
*1 ミッション付近にじみあり AROUND TRANSMISSION: OIL OOZING	
*2 縦シリンダー4本油漏れ、左R縦シリンダーロッド傷あり	
*2 VERTICAL CYLINDERS: OIL LEAKING,	
REAR LEFT VERTICAL CYLINDER ROD: SCRATCHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。