

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

|                 |                 |      |                     |       |        |
|-----------------|-----------------|------|---------------------|-------|--------|
| INSPECTION DATE | 2024/3/15       | MAKE | KATO                | MODEL | KR-75H |
| SERIAL No.      | PLATE : 6910147 |      | STAMP : KRC012-0147 |       |        |
| HR METER        | 6573            | HR   | Odometer            | 12607 | km     |
| TIRE SIZE       | 385/95R25       |      | YEAR                | YR    |        |

| ENGINE : MODEL                   | S/N   |
|----------------------------------|---|
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                            |
| Blow-By                          | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil                              | <input checked="" type="radio"/> FAIR · Attn                            |
| Exhaust Color                    | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>OPERATION PUMP</b>            |   |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                            |
| Power                            | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>COOLING SYSTEM</b>            |   |
| Radiator                         | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil Cooler                       | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>OPERATING SYSTEM</b>          |   |
| Computer                         | <input checked="" type="radio"/> OK · NG                                |
| Swing                            | <input checked="" type="radio"/> FAIR · Attn                            |
| Travel                           | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>TRANSMISSION</b>              |   |
| Transmission                     | <input checked="" type="radio"/> FAIR · Attn                            |
| No. OF GEARS                     | 4 GEARS   |
| No. of DRIVE WHEELS              | 6 WD  |
| <b>INTERIOR See Photos. 写真参照</b> |   |
| Operator's Seat                  | <input checked="" type="radio"/> FAIR · Attn                            |
| Inside Cover                     | <input checked="" type="radio"/> FAIR · Attn                            |
| Glasses                          | <input checked="" type="radio"/> FAIR · Attn                            |
| AirCon                           | <input checked="" type="radio"/> A/C · H/C · H only · C only · None     |
| <b>COMMENT</b>                   |   |
|                                  |   |

| BOOM   |  |
|--|--|
| No. of Section   | 6 SECTIONS                                   |
| CRACK/ENFORCEMENT  | <input checked="" type="radio"/> FAIR · Attn |
| DERRICKING CYL.  | <input checked="" type="radio"/> FAIR · Attn |
| EXTENSION CYL.   | <input checked="" type="radio"/> FAIR · Attn |
| JIB  | <input checked="" type="radio"/> YES · NO    |
| JIB TYPE   | STD · <input checked="" type="radio"/> PWR   |
| MAIN & SUB WIRE  | <input checked="" type="radio"/> YES · NO    |
| HOOK   | 75t, 35t, BALL                               |
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3  |
| <b>COMMENT</b>   |  |
| 左Fステアリングシリンダー油漏れあり   |  |
| FRONT LEFT STEERING CYLINDER: OIL LEAKING                            |  |
| <b>OUTRIGGERS</b>  |  |
| OUTRIGGERS   | X · <input checked="" type="radio"/> H       |
| OUTRIGGERS COND.   | <input checked="" type="radio"/> FAIR · Attn |
| <b>COMMENT</b>   |  |
| @SAKURA YARD   |  |
| 75t HOOK, HANGER × 2, WEIGHT   |  |
|  |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。