

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

| | | | | | |
|-----------------|--|------|---------|--|----------|
| INSPECTION DATE | 2024/3/14 | MAKE | KOMATSU | MODEL | D85EX-15 |
| SERIAL | 10092 | | STAMP | NOT FOUND | |
| HR METER | 11582 | HR | SHOE | 560G | YEAR YR |
| BLADE | STRAIGHT / ST/TILT / PAT / ANGLE / OTHER | | CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | |

| | |
|--|--|
| ENGINE : MODEL 6D125E-3 S/N 312600 | |
| Oil leakage | FAIR · Attn |
| Blow-By | FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | FAIR · Attn |
| Oil | FAIR · Attn |
| Exhaust Color | FAIR · Attn |
| US EPA | YES · NO |
| OPERATION PUMP | |
| Sound | FAIR · Attn |
| Oil leakage | FAIR · Attn |
| Power | FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | FAIR · Attn |
| Oil Cooler | FAIR · Attn |
| TRANSMISSION & TRAVEL | |
| T/M TYPE | PS · DD DIFF. STEERING YES · NO |
| Transmission | FAIR · Attn *1 |
| Travel | FAIR · Attn |
| INTERIOR See Photos. 写真参照 | |
| Operator's Seat | FAIR · Attn |
| Inside Cover | FAIR · Attn |
| Glasses | FAIR · Attn |
| AirCon | A/C · H/C · H only · C only · None |
| BLADE & CYLINDERS | |
| BLADE | FAIR · Attn |
| CYLD.(R) | FAIR · Attn |
| CYLD.(L) | FAIR · Attn |
| TILT CYLD | FAIR · Attn |
| ANGLE CYLD | FAIR · Attn |

| | | | |
|--|-------------|--------|-----|
| UNDERCARRIAGE See Photos. 写真参照 | | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 2 |
| COMMENT | | | |
| シューリンク固着あり TRACK LINKS: STUCK | | | |
| | | | |
| | | | |
| | | | |
| Ripper | MULTI · S/S | Shanks | PCS |
| Ripper CYLD. | FAIR · Attn | | |
| EQUALIZER BAR | FAIR · Attn | | |
| COMMENT | | | |
| *1 3速入るがすぐに2速に戻ってしまう | | | |
| *1 AUTOMATICALLY SHIFTING DOWN INTO THE 2nd GEAR | | | |
| AFTER SHIFTING INTO THE 3rd GEAR | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。