

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |   |      |         |                   |            |
|-----------------|---|------|---------|-------------------|------------|
| INSPECTION DATE | 2024/3/18                                     | MAKE | HITACHI | MODEL             | ZX225USR-3 |
| SERIAL          | HCM1U500A00222361                             |      | STAMP   | HCM1U500A00222361 |            |
| HR METER        | 9144  | HR   | YEAR    | YR                |            |
| CAB/CNP         | ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE | SHOE | 600G    |                   |            |

|  |  |   |
|--|--|---|
| <b>ENGINE : MODEL</b> 4HK1 S/N 700969                                | <b>UNDERCARRIAGE :</b> See Photos. 写真参照  |   |
| Oil leakage <input type="radio"/> FAIR · Attn                        | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4   |   |
| Blow-By <input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE | <b>COMMENT</b><br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>..... |   |
| Sound <input type="radio"/> FAIR · Attn                              |  |   |
| Oil <input type="radio"/> FAIR · Attn                                |  |   |
| Exhaust Color <input type="radio"/> FAIR · Attn                      |  |   |
| US EPA YES · <u>NO</u>   |  |   |
| <b>MAIN PUMP</b>   |  | BKT <input type="radio"/> STD / <input type="radio"/> SLOPE / NARROW / SKELETON / OTHER ( ) |
| Sound <input type="radio"/> FAIR · Attn                              |  | Lever LONG · <u>WRIST</u>   |
| Oil leakage <input type="radio"/> FAIR · Attn                        |  | Multi <input type="radio"/> MULTI · 2 · NO  |
| Power <input type="radio"/> FAIR · Attn                              |  | ARM-CRANE <input type="radio"/> YES · NO  |
| <b>COOLING SYSTEM</b>  |  | BLADE YES · <u>NO</u>   |
| Radiator <input type="radio"/> FAIR · Attn                           | OFFSET YES · <u>NO</u>   |   |
| Oil Cooler <input type="radio"/> FAIR · Attn                         | OFFSET Cylinder FAIR · Attn  |   |
| <b>OPERATING SYSTEM</b>  | Piping YES · <u>NO</u> Breaker only · Multi  |   |
| Swing <input type="radio"/> FAIR · Attn ガタあり SWING: LOOSE            | <b>COMMENT</b><br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>.....<br>..... |   |
| Travel <input type="radio"/> FAIR · Attn                             |  |   |
| <b>INTERIOR</b> See Photos. 写真参照                                     |  |   |
| Operator's Seat <input type="radio"/> FAIR · Attn                    |  |   |
| Inside Cover <input type="radio"/> FAIR · Attn                       |  |   |
| Glasses <input type="radio"/> FAIR · Attn                            |  |   |
| AirCon <u>A/C</u> · H/C · H only · C only · None                     |  |   |
| <b>BOOM / ARM / BKT</b>  |  | RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4                      |
| Boom <input type="radio"/> FAIR · Attn                               |  |   |
| Boom Cylinder <input type="radio"/> FAIR · Attn                      |  |   |
| Arm <input type="radio"/> FAIR · Attn                                |  |   |
| Arm Cylinder <input type="radio"/> FAIR · Attn                       |  |   |
| BKT <input type="radio"/> FAIR · Attn                                |  |   |
| BKT Cylinder <input type="radio"/> FAIR · Attn                       |  |   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。