

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/3/18	MAKE	BOMAG	MODEL	BW131ACW
SERIAL	230494		STAMP	N131AC230494	
HR METER	2841	HR	Odometer	-	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		TIRE SIZE	10.5/80-16	

ENGINE : MODEL	S/N	UNDERCARRIAGE :	See Photos. 写真参照
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	<input checked="" type="radio"/> FAIR · Attn	COMMENT	
Sound	<input checked="" type="radio"/> FAIR · Attn	<div style="border: 1px solid black; height: 100%; width: 100%;"></div>	
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD		
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn		
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn		
INTERIOR		See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	<div style="border: 1px solid black; height: 100%; width: 100%;"></div>	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
OTHERS		<div style="border: 1px solid black; height: 100%; width: 100%;"></div>	
Vibratory	<input checked="" type="radio"/> FAIR · Attn		
Watering	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn 不良 MALFUNCTION		
Articulate	<input checked="" type="radio"/> FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。