

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/3/19	MAKE	SAKAI	MODEL	TS160-2
SERIAL	50260		STAMP	1TS8-50260	
HR METER	1766	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		<input checked="" type="radio"/> NONE	TIRE SIZE	9.5/65-15

ENGINE : MODEL	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
OTHERS		
Vibratory	FAIR · Attn	
Watering	FAIR · <input checked="" type="radio"/> Attn *1	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
*1 前方散水ノズル一部散水不良	
*1 SOME FRONT WATERING NOZZLES: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。