INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/19	MAKE	SUMITOMO	MODEL	SH120-5
SERIAL	SMT120A5J00LR1465			STAMP	SMT120A5J00LR1465
HR METER	11777 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G FLAT

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	*1
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	クラック、補修跡あり CRACKED, REPAIRED
Boom Cylinder	FAIR・Attn	右油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	FAIR・Attn	補強跡あり REINFORCED
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi 5

COMMENT

ハイCAB HIGH CAB

12mスーパーロング 12m SUPER LONG

ボディヘコミ大 BODY: MUCH DENT

左サイドカバーラッチ不良 LEFT SIDE COVER LATCH: MALFUNCTION

*1 ガタあり、ブレーキ甘い SWING: LOOSE, BRAKE: LOOSE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。