

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/3/19	MAKE	CAT	MODEL	320D2
SERIAL	CAT0320DASNS00409		STAMP	CAT0320DASNS00409	
HR METER	7671 / 7681	HR	YEAR	YR	
CAB/CNP	ROPS CAB (CAB) / ROPS CNP / CNP / NONE	SHOE		600G	

ENGINE : MODEL	S/N
Oil leakage	(FAIR) · Attn
Blow-By	(FAIR) · Attn    A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn
Oil	(FAIR) · Attn
Exhaust Color	(FAIR) · Attn
US EPA	(YES) · NO
<b>MAIN PUMP</b>	
Sound	(FAIR) · Attn
Oil leakage	(FAIR) · Attn
Power	(FAIR) · Attn
<b>COOLING SYSTEM</b>	
Radiator	(FAIR) · Attn
Oil Cooler	(FAIR) · Attn
<b>OPERATING SYSTEM</b>	
Swing	(FAIR) · Attn
Travel	(FAIR) · Attn
<b>INTERIOR    See Photos. 写真参照</b>	
Operator's Seat	(FAIR) · Attn
Inside Cover	(FAIR) · Attn
Glasses	(FAIR) · Attn
AirCon	(A/C) · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	(FAIR) · Attn
Boom Cylinder	(FAIR) · Attn
Arm	(FAIR) · Attn
Arm Cylinder	(FAIR) · Attn
BKT	(FAIR) · Attn
BKT Cylinder	(FAIR) · Attn

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b> 右側シューリンク固着あり RIGHT TRACK LINKS: STUCK	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · (WRIST)
Multi	(MULTI) · 2 · NO
ARM-CRANE	(YES) · NO    プレート欠、フック欠 NO PLATE, NO HOOK
BLADE	YES · (NO)
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	(YES) · NO    Breaker only · (Multi)
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。