

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/19	MAKE	HITACHI	MODEL	ZX200-3
SERIAL	HCM1U100A00212955		STAMP	HCM1U100A00212955	
HR METER	7458	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 4HK1 **S/N** 453352

Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	
Blow-By	<input checked="" type="radio"/> FAIR	· Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	· Attn	
Oil	<input checked="" type="radio"/> FAIR	· Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	· Attn	
US EPA	<input checked="" type="radio"/> YES	· NO	

MAIN PUMP

Sound	<input checked="" type="radio"/> FAIR	· Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	
Power	<input checked="" type="radio"/> FAIR	· Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	· Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	· Attn	

OPERATING SYSTEM

Swing	<input checked="" type="radio"/> FAIR	· Attn	
Travel	<input checked="" type="radio"/> FAIR	· Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR	· Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	· Attn	
Glasses	<input checked="" type="radio"/> FAIR	· Attn	
AirCon	<input checked="" type="radio"/> A/C	· H/C · H only · C only · None	

BOOM / ARM / BKT

Boom	<input checked="" type="radio"/> FAIR	· Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	· Attn	右油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	<input checked="" type="radio"/> FAIR	· Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	· Attn	
BKT	<input checked="" type="radio"/> FAIR	· Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	· Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO *1
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO <input checked="" type="radio"/> Breaker only · Multi

COMMENT

E/Gフードラッチ不良 ENGINE HOOD LATCH: MALFUNCTION
*1 プレート欠、MLクレーン故障警告あり
*1 NO PLATE, WARNING DISPLAY FOR ML CRANE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。