

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/3/22	MAKE	HITACHI	MODEL	ZX200LC
SERIAL	HCM1G600L00106544		STAMP	HCM1G600L00106544	
HR METER	40139	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · Attn	
Blow-By	FAIR · <u>Attn</u>	A LITTLE · <u>MIDDLE</u> · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · <u>NO</u>	文字読めない STICKER: UNREADABLE

<b>MAIN PUMP</b>	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn

<b>COOLING SYSTEM</b>	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn

<b>OPERATING SYSTEM</b>	
Swing	FAIR · <u>Attn</u> ガタあり SWING: LOOSE
Travel	FAIR · Attn

<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり TORN
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None

<b>BOOM / ARM / BKT</b>	
Boom	FAIR · Attn
Boom Cylinder	FAIR · <u>Attn</u> 右油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · <u>Attn</u> ピンガタあり PIN: LOOSE
BKT Cylinder	FAIR · Attn

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

**COMMENT**  
右シューリンク固着あり RIGHT TRACK LINKS: STUCK

BKT	STD / SLOPE / NARROW / SKELETON / <u>OTHER</u> (FORK GRAB)
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>

**COMMENT**

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。