

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/3/22	MAKE	MITSUBISHI	MODEL	BD2J
SERIAL	JB110191			STAMP	2B110191
HR METER	2189	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · <input checked="" type="radio"/> DD	DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	*1
INTERIOR See Photos. 写真参照		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
BLADE & CYLINDERS		
BLADE	<input type="radio"/> FAIR · Attn	
CYLD.(R)	<input type="radio"/> FAIR · Attn	
CYLD.(L)	<input type="radio"/> FAIR · Attn	
TILT CYLD	<input type="radio"/> FAIR · Attn	
ANGLE CYLD	<input type="radio"/> FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input type="radio"/> FAIR · Attn		
COMMENT			
*1 後進時右足ステアリング切りづらい			
*1 RIGHT TRACK: HARD TO TURN DURING TRAVELING BACKWARD			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。