

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/22	MAKE	KOBELCO	MODEL	SK135SRD-5
SERIAL	YY08041174		STAMP	YY08041174	
HR METER	10480	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G FLAT	

ENGINE : MODEL 4JJ1 S/N

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	文字不鮮明 STICKER: BLURRED

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	油漏れあり OIL LEAKING
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	*1
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5 *2

COMMENT

コントロールバルブ周り油漏れあり AROUND CONTROL VALVE: OIL LEAKING
左サイドカバーラッチ不良 LEFT SIDE COVER LATCH: MALFUNCTION
ボディへコミ多数あり BODY: A LITTLE DEFORMED
アタッチメントなし WITHOUT ATTACHMENT
*1 ドア下部アクリル板 LOWER DOOR GLASS: ACRYLIC BOARD
*2 全てメクラ欠(油漏れ小) NO CAPS (OIL LEAKING)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。