

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2023/8/21	CATEGORY	CNP for PC20-5		
MAKE	KOMATSU		MODEL	UNKNOWN	
SERIAL	-		STAMP	-	
HR METER	-	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE		TIRE

ENGINE	MODEL	S/N
Oil leakage	FAIR · Attn	Oil FAIR · Attn
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE Exhaust Color FAIR · Attn
Sound	FAIR · Attn	EPA YES · NO

CONDITION	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	
--	---	--

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。