

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/1	MAKE	CAT	MODEL	311CU
SERIAL	CAT0311CKCLK02006		STAMP	CAT0311CKCLK02006	
HR METER	217 + 2658	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE	600G		

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2"><b>ENGINE : MODEL</b></td> <td style="text-align: center;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td><input checked="" type="radio"/> YES · NO</td> <td></td> </tr> <tr> <td colspan="3"><b>MAIN PUMP</b></td> </tr> <tr> <td>Sound</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Power</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3"><b>COOLING SYSTEM</b></td> </tr> <tr> <td>Radiator</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3"><b>OPERATING SYSTEM</b></td> </tr> <tr> <td>Swing</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3"><b>INTERIOR</b>    See Photos. 写真参照</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · <input checked="" type="radio"/> Attn</td> <td>破れあり TORN</td> </tr> <tr> <td>Inside Cover</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>AirCon</td> <td><input checked="" type="radio"/> A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="3"><b>BOOM / ARM / BKT</b></td> </tr> <tr> <td>Boom</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Boom Cylinder</td> <td>FAIR · <input checked="" type="radio"/> Attn</td> <td>左右油にじみあり OIL OOZING</td> </tr> <tr> <td>Arm</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>Arm Cylinder</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>BKT</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> <tr> <td>BKT Cylinder</td> <td><input checked="" type="radio"/> FAIR · Attn</td> <td></td> </tr> </table>	<b>ENGINE : MODEL</b>		S/N	Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Sound	<input checked="" type="radio"/> FAIR · Attn		Oil	<input checked="" type="radio"/> FAIR · Attn		Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		US EPA	<input checked="" type="radio"/> YES · NO		<b>MAIN PUMP</b>			Sound	<input checked="" type="radio"/> FAIR · Attn		Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Power	<input checked="" type="radio"/> FAIR · Attn		<b>COOLING SYSTEM</b>			Radiator	<input checked="" type="radio"/> FAIR · Attn		Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		<b>OPERATING SYSTEM</b>			Swing	<input checked="" type="radio"/> FAIR · Attn		Travel	<input checked="" type="radio"/> FAIR · Attn		<b>INTERIOR</b> See Photos. 写真参照			Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり TORN	Inside Cover	<input checked="" type="radio"/> FAIR · Attn		Glasses	<input checked="" type="radio"/> FAIR · Attn		AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None		<b>BOOM / ARM / BKT</b>			Boom	<input checked="" type="radio"/> FAIR · Attn		Boom Cylinder	FAIR · <input checked="" type="radio"/> Attn	左右油にじみあり OIL OOZING	Arm	<input checked="" type="radio"/> FAIR · Attn		Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn		BKT	<input checked="" type="radio"/> FAIR · Attn		BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2"><b>UNDERCARRIAGE :</b>    See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">BKT</div> <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER (    )                 </td> </tr> <tr> <td>Lever</td> <td>LONG · <input checked="" type="radio"/> WRIST</td> </tr> <tr> <td>Multi</td> <td><input checked="" type="radio"/> MULTI · 2 · NO</td> </tr> <tr> <td>ARM-CRANE</td> <td>YES · <input checked="" type="radio"/> NO</td> </tr> <tr> <td>BLADE</td> <td>YES · <input checked="" type="radio"/> NO</td> </tr> <tr> <td>OFFSET</td> <td>YES · <input checked="" type="radio"/> NO</td> </tr> <tr> <td>OFFSET Cylinder</td> <td>FAIR · Attn</td> </tr> <tr> <td>Piping</td> <td><input checked="" type="radio"/> YES · NO    Breaker only · <input checked="" type="radio"/> Multi</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">RUST of BODY</div> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                 </td> </tr> <tr> <td colspan="2" style="text-align: right;">3</td> </tr> </table>	<b>UNDERCARRIAGE :</b> See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	<b>COMMENT</b>		<div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">BKT</div> <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER (    )		Lever	LONG · <input checked="" type="radio"/> WRIST	Multi	<input checked="" type="radio"/> MULTI · 2 · NO	ARM-CRANE	YES · <input checked="" type="radio"/> NO	BLADE	YES · <input checked="" type="radio"/> NO	OFFSET	YES · <input checked="" type="radio"/> NO	OFFSET Cylinder	FAIR · Attn	Piping	<input checked="" type="radio"/> YES · NO    Breaker only · <input checked="" type="radio"/> Multi	<b>COMMENT</b>		<div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">RUST of BODY</div> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
<b>ENGINE : MODEL</b>		S/N																																																																																																																		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																		
Sound	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Oil	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
US EPA	<input checked="" type="radio"/> YES · NO																																																																																																																			
<b>MAIN PUMP</b>																																																																																																																				
Sound	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Oil leakage	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Power	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
<b>COOLING SYSTEM</b>																																																																																																																				
Radiator	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
<b>OPERATING SYSTEM</b>																																																																																																																				
Swing	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Travel	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
<b>INTERIOR</b> See Photos. 写真参照																																																																																																																				
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり TORN																																																																																																																		
Inside Cover	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Glasses	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None																																																																																																																			
<b>BOOM / ARM / BKT</b>																																																																																																																				
Boom	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Boom Cylinder	FAIR · <input checked="" type="radio"/> Attn	左右油にじみあり OIL OOZING																																																																																																																		
Arm	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
BKT	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn																																																																																																																			
<b>UNDERCARRIAGE :</b> See Photos. 写真参照																																																																																																																				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																			
<b>COMMENT</b>																																																																																																																				
<div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">BKT</div> <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER (    )																																																																																																																				
Lever	LONG · <input checked="" type="radio"/> WRIST																																																																																																																			
Multi	<input checked="" type="radio"/> MULTI · 2 · NO																																																																																																																			
ARM-CRANE	YES · <input checked="" type="radio"/> NO																																																																																																																			
BLADE	YES · <input checked="" type="radio"/> NO																																																																																																																			
OFFSET	YES · <input checked="" type="radio"/> NO																																																																																																																			
OFFSET Cylinder	FAIR · Attn																																																																																																																			
Piping	<input checked="" type="radio"/> YES · NO    Breaker only · <input checked="" type="radio"/> Multi																																																																																																																			
<b>COMMENT</b>																																																																																																																				
<div style="border: 1px solid black; border-radius: 10px; padding: 2px; display: inline-block;">RUST of BODY</div> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																				
3																																																																																																																				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。