

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/3	MAKE	YANMAR	MODEL	B6-6
SERIAL	60633B		STAMP	60633B	
HR METER	6835	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	400R	

<b>ENGINE : MODEL</b> 4TNV88 <b>S/N</b> 27330	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
<b>MAIN PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
<b>OPERATING SYSTEM</b>	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
<b>BOOM / ARM / BKT</b>	
Boom	<u>FAIR</u> · Attn
Boom Cylinder	<u>FAIR</u> · Attn
Arm	<u>FAIR</u> · Attn
Arm Cylinder	<u>FAIR</u> · Attn
BKT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO 警告音あり WARNING SOUND: ON
BLADE	<u>YES</u> · NO
OFFSET	<u>YES</u> · NO
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
操作パネル不良 OPERATION PANEL: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。