

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/4/12	MAKE	FURUKAWA	MODEL	FL304-2
SERIAL	5751		STAMP	F24-5751	
HR METER	2879	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	15.5/60-18	

ENGINE : MODEL		S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD		
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn		
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	切れあり CUTS	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None		
FRONT & CYLINDERS			
Arm	<input checked="" type="radio"/> FAIR · Attn		
Bell crank	<input checked="" type="radio"/> FAIR · Attn		
Bucket	<input checked="" type="radio"/> FAIR · Attn		
Articulate	<input checked="" type="radio"/> FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
STEERING TYPE	<input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT	
エンジンボンネット取付部ガタあり LATCHES OF ENGINE HOOD: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。