

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/5/9	MAKE	HITACHI	MODEL	EX200-5E
SERIAL	14M-81968		STAMP	14M-81968	
HR METER	9262	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
<b>MAIN PUMP</b>		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<u>FAIR</u> · <u>Attn</u>	ガタあり LOOSE
Travel	<u>FAIR</u> · <u>Attn</u>	HIスイッチ不良 HI SWITCH: MALFUNCTION
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<u>FAIR</u> · <u>Attn</u>	破れあり HUGE CUTS
Inside Cover	<u>FAIR</u> · <u>Attn</u>	汚れあり DIRTY
Glasses	<u>FAIR</u> · <u>Attn</u>	F下ガラスなし LOWER WINDSHIELD: MISSING
AirCon	<u>A/C</u> · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON / <u>OTHER</u> (FORK GRAB)
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
<b>COMMENT</b>	
ドアラッチ不良 (閉じない) DOOR LATCH: MALFUNCTION (UNABLE TO SHUT)	
エキゾーストパイプ排気漏れあり EXHAUST PIPE: EXHAUST LEAKING	
オートアイドルリング不良 AUTO IDLING: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。