

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/6/12	MAKE	YANMAR	MODEL	VIO17
SERIAL	0E563		STAMP	0E563	
HR METER	136	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	230R	

ENGINE : MODEL		S/N	E8067
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn		
Inside Cover	<input type="radio"/> FAIR · Attn		
Glasses	<input type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR · Attn		
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn		
Arm	<input checked="" type="radio"/> FAIR · Attn		
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn		
BKT	<input checked="" type="radio"/> FAIR · Attn		
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
可変脚 VARIABLE WIDTH UNDERCARRIGE	
<hr/> <hr/> <hr/> <hr/> <hr/>	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · <input checked="" type="radio"/> 2 · <input type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	<input checked="" type="radio"/> YES · <input type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	<input type="radio"/> FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
<hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。