

INSPECTION SHEET 検品書  
ROLLER ローラー

INSPECTION DATE	2024/6/13	MAKE	SAKAI	MODEL	TW502
SERIAL	10662		STAMP	VTW31-10662	
HR METER	2975	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			TIRE SIZE	10.5/80-16

<b>ENGINE : MODEL</b> D1503 <b>S/N</b> 06Y0932	<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	<b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 3	
Blow-By <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE	<b>COMMENT</b>	
Sound <input checked="" type="radio"/> FAIR · Attn		
Oil <input checked="" type="radio"/> FAIR · Attn		
Exhaust Color <input checked="" type="radio"/> FAIR · Attn		
US EPA <input checked="" type="radio"/> YES · NO		
<b>OPERATION PUMP</b>		
Sound <input checked="" type="radio"/> FAIR · Attn		
Oil leakage <input checked="" type="radio"/> FAIR · Attn		
Power <input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>		
Radiator <input checked="" type="radio"/> FAIR · Attn		
Oil Cooler <input checked="" type="radio"/> FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE <input checked="" type="radio"/> PS · DD		
Transmission <input checked="" type="radio"/> FAIR · Attn		
Travel <input checked="" type="radio"/> FAIR · Attn		
FOOT BRAKE <input checked="" type="radio"/> FAIR · Attn		
PARKING BRAKE <input checked="" type="radio"/> FAIR · Attn		
<b>INTERIOR</b> See Photos. 写真参照		
Operator's Seat <input checked="" type="radio"/> FAIR · Attn 破れあり CUTS		
Inside Cover <input checked="" type="radio"/> FAIR · Attn		
Glasses <input checked="" type="radio"/> FAIR · Attn		
AirCon A/C · H/C · H only · C only · <u>None</u>		
<b>OTHERS</b>		
Vibratory <input checked="" type="radio"/> FAIR · Attn		
Watering <input checked="" type="radio"/> FAIR · Attn		
Articulate <input checked="" type="radio"/> FAIR · Attn	<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。