

**INSPECTION SHEET 検品書**  
**ROLLER ローラー**

INSPECTION DATE	2024/6/19	MAKE	SAKAI	MODEL	TW500W-1
SERIAL	SOME LETTERS: UNREADABLE			STAMP	VTW15-20988
HR METER	3736	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			TIRE SIZE	10.5/80-16

ENGINE : MODEL	S/N	UNDERCARRIAGE :	See Photos. 写真参照
Oil leakage	<u>FAIR</u> · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
Blow-By	<u>FAIR</u> · Attn	COMMENT	
Sound	<u>FAIR</u> · Attn	<div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div> <div style="border-bottom: 1px dotted black; height: 18px; margin-bottom: 2px;"></div>	
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
<b>OPERATION PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<u>PS</u> · DD		
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
FOOT BRAKE	<u>FAIR</u> · Attn		
PARKING BRAKE	<u>FAIR</u> · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<u>FAIR</u> · <u>Attn</u> 背もたれ外れ BACKREST: NOT ATTACHED		
Inside Cover	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>OTHERS</b>			
Vibratory	<u>FAIR</u> · Attn		
Watering	<u>FAIR</u> · Attn		
Articulate	<u>FAIR</u> · Attn		
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。