

INSPECTION SHEET 検品書  
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/7/1	MAKE	YANMAR	MODEL	C30R-3
SERIAL	31140		STAMP	31140	
HR METER	851	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	320R	TIRE

<b>ENGINE : MODEL</b> 4TNV88C <b>S/N</b> 45381	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
<b>OPERATION PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	<u>PS</u> · DD No. OF GEARS GEARS
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
Swing	<u>FAIR</u> · Attn
Articulate	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	<u>FAIR</u> · Attn
<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>

<b>MAIN FRAME</b>	
MAIN FLAME	<u>FAIR</u> · Attn
<b>VESSEL</b>	
VESSEL	<u>FAIR</u> · Attn
REAR GATE TYPE	<u>NORMAL</u> · L-GATE (FLAT)
REAR GATE	<u>FAIR</u> · Attn
<b>UNDERCARRIAGE:</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。