

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/7/2	MAKE	KUBOTA	MODEL	U-45
SERIAL	JKUU0453L00H30054		STAMP	30054	
HR METER	5385	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		S/N	5N2986
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
MAIN PUMP			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
OPERATING SYSTEM			
Swing	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
BOOM / ARM / BKT			
Boom	<u>FAIR</u> · Attn		
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO アングル式 ANGLE STYLE
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u> *1
COMMENT	
*1 S/W入れても油圧が掛からない	
*1 UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。