

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/7/4	MAKE	CAT	MODEL	301.5CR
SERIAL	CAT03015KRAA01368		STAMP	CAT03015KRAA01368	
HR METER	2552	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	250R	

<b>ENGINE : MODEL</b>	<b>S/N</b>	
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
<b>MAIN PUMP</b>		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
<b>COOLING SYSTEM</b>		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
<b>OPERATING SYSTEM</b>		
Swing	FAIR	Attn
Travel	FAIR	Attn
<b>INTERIOR</b>	<b>See Photos. 写真参照</b>	
Operator's Seat	FAIR	Attn
Inside Cover	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C
	H only	C only
	None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn
BKT Cylinder	FAIR	Attn

<b>UNDERCARRIAGE :</b>		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
<b>COMMENT</b>			
右トラックフレーム伸縮不良			
RIGHT EXPANDABLE CYLINDER: MALFUNCTION			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	*1
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi 4
<b>COMMENT</b>			
*1 スプレッド溶接あり、畳めない			
*1 EXTENSION PARTS: WELDED (UNABLE TO FOLD)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。