INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/16	MAKE	KOMATSU	MODEL	PC35MR-2
SERIAL	9023	STAMP	KMTPC096J05009023		
HR METER	4154 HR	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / (ROPS CNP) / CNP / NONE	SHOE	300R		

ENGINE : MODEL S/N		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	FAIR · (Attn)	水漏れ大 MUCH WATER LEAKING
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · (Attn)	破れ大 HUGE CUTS
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	FAIR · (Attn)	亀裂2箇所あり CRACKED
Arm Cylinder	(FAIR) · Attn	
BKT	FAIR · (Attn)	ガタ大 MUCH LOOSE
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO	Breaker only · (Multi)
COMMENT		
E/G付近にじみあり(場所不特定)		
AROUND ENGINE: OIL OOZING (LEAK SPOTS: UNKNOWN)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。