

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/5/27	MAKE	YANMAR	MODEL	V3-6
SERIAL	62604		STAMP	NOT FOUND	
HR METER	E1391	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <b>CNP</b> / NONE			TIRE SIZE	12.5/70-16

<b>ENGINE : MODEL</b>	<b>S/N</b>		N2233
Oil leakage	<b>FAIR</b> · Attn		
Blow-By	<b>FAIR</b> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<b>FAIR</b> · Attn		
Oil	<b>FAIR</b> · Attn		
Exhaust Color	<b>FAIR</b> · Attn		
US EPA	YES · <b>(NO)</b>		
<b>OPERATION PUMP</b>			
Sound	<b>FAIR</b> · Attn		
Oil leakage	<b>FAIR</b> · Attn		
Power	<b>FAIR</b> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<b>FAIR</b> · Attn		
Oil Cooler	<b>FAIR</b> · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<b>PS</b> · DD		
Transmission	<b>FAIR</b> · Attn		
Travel	<b>FAIR</b> · Attn		
FOOT BRAKE	<b>FAIR</b> · Attn		
PARKING BRAKE	<b>FAIR</b> · Attn	*1	
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<b>FAIR</b> · Attn		
Inside Cover	<b>FAIR</b> · Attn		
Glasses	<b>FAIR</b> · Attn		
AirCon	A/C · H/C · H only · C only · <b>(None)</b>		
<b>FRONT &amp; CYLINDERS</b>			
Arm	<b>FAIR</b> · Attn	*2	
Bell crank	<b>FAIR</b> · Attn		
Bucket	<b>FAIR</b> · Attn	コンクリート付着大 MUCH CONCRETE STAINS	
Articulate	<b>FAIR</b> · Attn		

<b>UNDERCARRIAGE :</b>	See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		
<b>COMMENT</b>			
コンクリート付着大 MUCH CONCRETE STAINS			
STEERING TYPE	<b>WHEEL STEERING</b> / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES · <b>(NO)</b>		
<b>ATTACHMENTS</b>			
STD BKT	<b>(YES)</b> · OTHER		
BLADE	YES · <b>(NO)</b> Piping for Tilt YES · <b>(NO)</b>		
<b>COMMENT</b>			
E/G周りコンクリート付着大 AROUND ENGINE: MUCH CONCRETE STAINS			
マフラー一部折れあり MUFFLER: CHIPPED OFF			
HRメーターストップ HR METER: STOPPED			
*1 ペダル: ロック状態を維持できない(土嚢でペダルを押さえれば効く)			
*1 PEDAL: UNABLE TO KEEP THE LOCKED POSITION			
(NEED TO APPLY SOME WEIGHT LIKE A SANDBAG TO WORK)			
*2 左シリンダーにじみあり LEFT CYLINDER: OIL OozING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。