

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/6/19	MAKE	HITACHI	MODEL	ZX200-3
SERIAL	HCM1U100V00221296		STAMP	HCM1U100V00221296	
HR METER	6562	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE	600G		

<b>ENGINE : MODEL</b> 4HK1 <b>S/N</b>	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
<b>MAIN PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
<b>OPERATING SYSTEM</b>	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	<u>FAIR</u> · Attn
Boom Cylinder	<u>FAIR</u> · <u>Attn</u> 左右にじみあり CYLINDERS: OIL OOZING
Arm	<u>FAIR</u> · Attn
Arm Cylinder	<u>FAIR</u> · Attn
BKT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
<b>COMMENT</b>	
スィベルか旋回のどちらかから油漏れ小	
SWIVEL or SWING PART: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。