

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/7/3	MAKE	CAT	MODEL	311DRR-MS
SERIAL	CAT0311DKAKW00649		STAMP	CAT0311DKAKW00649	
HR METER	UNKNOWN / 5948	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G		

ENGINE : MODEL	C4.2	S/N	JKH08643
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR · Attn		
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn	Fひび割れあり UPPER WINDSHIELD: CRACKED	
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
BKT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左走行モーター付近油漏れあり AROUND LEFT TRAVEL MOTOR: OIL LEAKING	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 3
COMMENT	
HRメーター片方不良 ONE OF HR METERS: MALFUNCTION A/Cベルトなし A/C: NO BELT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。