

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2024/8/7	CATEGORY	ROTATABLE CUTTER FOR 0.7m3			
MAKE	HITACHI		MODEL	S-HSC100S		
SERIAL	U578		STAMP			
HR METER	HR	Odometer	km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	TIRE		

ENGINE	MODEL	S/N
Oil leakage	FAIR ・ Attn	Oil FAIR ・ Attn
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA YES ・ NO

CONDITION	FAIR ・ Attn
-----------	-------------

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
--	--

COMMENT

80φ × 310mm

回転しない UNABLE TO ROTATE

右シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。