

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/8/7	MAKE	KIC	MODEL	MCR-T5
SERIAL No.	PLATE : MC117		STAMP	NOT FOUND	
HR METER	1670	HR	SHOE	300R	YEAR YR

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn

OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn

COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn

OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn

BOOM	
MAIN BOOM	*1
BOOM TOTAL	8.5m
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	
TOWER	5段テレスコ 9.3m 5 SECTIONS 9.3m

INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	
WEIGHT	
HOOK	
LIFTER	<input checked="" type="radio"/> YES · <input checked="" type="radio"/> NO

COMMENT	
*1 TOP 0.95m × 1 BOTTOM 1.55m × 1 BOOM 2.25m × 2, 1.5m × 1	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。