

**INSPECTION SHEET 検品書  
FORK LIFT フォークリフト**

INSPECTION DATE	2024/10/21	MAKE	KOMATSU	MODEL	FD70HD-7
SERIAL	44033		STAMP	M16?-44033 SOME LETTER: UNREADABLE	
HR METER	15157	HR	Odometer	-	km YEAR YR
CAB/CNP	CAB / <u>CNP</u> / NONE		TIRE SIZE	8.25-15	
MAX LIFTING HEIGHT	3.0	m	<u>VIEW</u> MONO	FORK LENGTH	2050 mm
FORK SPEC	フォークシフト POSITIONER				

ENGINE : MODEL	S/N
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · <u>Attn</u> 白煙あり WHITE FUMES
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn
PARKING BRAKE	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn 破れあり CUTS
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
HYDRAULICS	
MAST Cylinder	<u>FAIR</u> · Attn
TILT Cylinder	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。