

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/10/21	MAKE	CAT	MODEL	CS-563C
SERIAL	4LN01071			STAMP	4LN01071
HR METER	5653	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.1-26R3

ENGINE : MODEL 3116DIT S/N 4TF56946	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage <input type="radio"/> FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By <input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE	COMMENT	
Sound <input type="radio"/> FAIR · Attn		
Oil <input type="radio"/> FAIR · Attn		
Exhaust Color <input type="radio"/> FAIR · Attn		
US EPA <input type="radio"/> YES · NO		
OPERATION PUMP		
Sound <input type="radio"/> FAIR · Attn		
Oil leakage <input type="radio"/> FAIR · Attn		
Power <input type="radio"/> FAIR · Attn		
COOLING SYSTEM		
Radiator <input type="radio"/> FAIR · Attn		
Oil Cooler <input type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL		
T/M TYPE <input type="radio"/> PS · DD		
Transmission <input type="radio"/> FAIR · Attn		
Travel <input type="radio"/> FAIR · Attn		
FOOT BRAKE <input type="radio"/> FAIR · Attn		
PARKING BRAKE <input type="radio"/> FAIR · Attn		
INTERIOR See Photos. 写真参照		
Operator's Seat <input type="radio"/> FAIR · Attn 破れあり CUTS		
Inside Cover <input type="radio"/> FAIR · Attn		
Glasses <input type="radio"/> FAIR · Attn		
AirCon A/C · H/C · H only · <input checked="" type="radio"/> C only · None		
OTHERS		
Vibratory <input type="radio"/> FAIR · Attn		
Watering <input type="radio"/> FAIR · Attn		
Articulate <input type="radio"/> FAIR · Attn ガタあり LOOSE	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。