

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/19	MAKE	CAT	MODEL	308CCR
SERIAL	CAT0308CECPE02924		STAMP	CAT0308CECPE02924	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB	(CAB)	ROPS CNP / CNP / NONE	SHOE	450G PADS

ENGINE : MODEL	4M40	S/N
Oil leakage	(FAIR)	Attn
Blow-By	(FAIR)	Attn A LITTLE · MIDDLE · SEVERE
Sound	(FAIR)	Attn
Oil	(FAIR)	Attn
Exhaust Color	(FAIR)	Attn
US EPA	(YES)	NO
MAIN PUMP		
Sound	(FAIR)	Attn
Oil leakage	(FAIR)	Attn
Power	(FAIR)	(Attn) 弱い WEAK POWER
COOLING SYSTEM		
Radiator	(FAIR)	Attn
Oil Cooler	(FAIR)	Attn
OPERATING SYSTEM		
Swing	(FAIR)	Attn
Travel	(FAIR)	Attn
INTERIOR	See Photos. 写真参照	
Operator's Seat	(FAIR)	Attn
Inside Cover	(FAIR)	Attn
Glasses	(FAIR)	Attn
AirCon	(A/C)	H/C · H only · C only · None
BOOM / ARM / BKT		
Boom	(FAIR)	Attn
Boom Cylinder	(FAIR)	Attn
Arm	(FAIR)	Attn
Arm Cylinder	(FAIR)	Attn
BKT	(FAIR)	(Attn) 石灰付着あり LIME STAINS
BKT Cylinder	(FAIR)	Attn

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG	(WRIST)
Multi	(MULTI)	2 · NO
ARM-CRANE	(YES)	NO
BLADE	(YES)	NO
OFFSET	YES	(NO)
OFFSET Cylinder	FAIR	Attn
Piping	YES	(NO) Breaker only · Multi
COMMENT	HRメーター故障あり HR METER: MALFUNCTION 作動油白濁あり HYDRAULIC OIL: CLOUDY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。