

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/9/17	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300C00061289		STAMP	HCM1P300C00061289	
HR METER	4623	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	450G	

<b>ENGINE : MODEL</b>	4LE2	<b>S/N</b>	254597
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	<u>YES</u> · NO		
<b>MAIN PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>OPERATING SYSTEM</b>			
Swing	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	<u>A/C</u> · H/C · H only · C only · None		
<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · Attn		
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
.....	
.....	
.....	
.....	
.....	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。